



GLASS BEADING:

Glass beads of 60-90 sieve, blast the weld and surrounding area. This cleans the area and gives a satin appearance similar to a 2B finish. The entire surface can be blasted or selected areas can be masked, giving a banded appearance.

